



**LEGEND**

	Unknown (Inferred to be Colluvium)
	Colluvium
	Fluvial gravel
	Bedrock
	Landslide/scree deposit

- NOTES:**
1. The debris slide covers the whole of the concave slope, but not along the track itself. Material is bedrock derived.
  2. Ground conditions are accurate at investigation locations & are inferred between test locations & may vary from the profile shown
  3. Western & Eastern parts of section are offset by approx. 40m due to imperceptible gorge
  4. Ground Profile obtained from a combination of T&T Abney Survey & topographic contours on upper slopes (NZMS 1:50 000 series)

<p><b>Tonkin &amp; Taylor</b> Environmental &amp; Engineering Consultants D Auckland D Hamilton D Nelson D Wellington D Whangarei</p>	<p><b>TASMAN DISTRICT COUNCIL</b> GEOTECHNICAL PRE-FEASIBILITY ASSESSMENT Lee River Valley, Tasman Geotechnical Section – Site 2</p>
	<p>FIG. No. Figure 4</p>
<p>PROJECT No. 22032.002</p>	<p>REV. 0</p>